cofe

03500.014383

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

3 //			
In re Application of:)		
		Examiner: S. Ebrahimi	
HIROYUKI TAKAHASHI)		•
	:	Art Unit: 2626	
Appl. No.: 09/498,627)		
	:		
Filed: February 7, 2000)		
	:		Contro
For: INFORMATION PROCESSING)		Certificate
APPARATUS FOR DISPLAYING	:		APR 0 3 2006
DATA RELATED TO IMAGE)		_
FORMING APPARATUS, AND	:		of Correction
INFORMATION PROCESSING) ,		4
METHOD THEREFOR	:		
)		
the property of the second	:		
U.S. Patent No.: 6,864,991 B1)		e:
	:		
Issued: March 8, 2005)	March 8, 2006	
en e			
Commissioner for Patents			
P.O. Box 1450			

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-identified patent:

SHEET 36

Alexandria, VA 22313-1450

Figure 36, "ROOTER" (all occurrences) should read --ROUTER--.

COLUMN 1

Line 17, "4" should be deleted.

COLUMN 3

Line 54, "router 3205" should read --router 3605--; and Line 56, "line 3208" should read --line 3608--.

COLUMN 4

Line 55, "B-bit" should read --8-bit--; and Line 59, "Since" should read --since--.

COLUMN 5

Line 12, "K1/and" should read --K1 and--.

COLUMN 6

Line 11, "bitmapped" should read --bit-mapped--.

COLUMN 7

Line 44, "black (B)" should read --black (K)--.

COLUMN 9

Line 51, "above described" should read --above-described--.

COLUMN 10

Line 8, "configuration tab 1207" should read --configuration tab 1206--; Line 45, "were are" should read --have been--; Line 58, "above described" should read --above-described--; and

Line 64, "17 cm" should read --17 in--.

COLUMN 11

Line 23, "Buttons 1310 to 1309" should read --Buttons 1303 to 1309--;

Line 48, "Qn," should read --on,--; and

Line 63, "cursor 150" should read --cursor 1510--.

COLUMN 12

Line 16, "1903. Thus" should read --1903, thus--;

Line 55, "london" should read -- London--; and

Line 59, "client distance." should read --client.--.

COLUMN 14

Line 28, "step 3402" should read --step S3402--; and

Line 36, "elapses," should be deleted.

COLUMN 15

Line 23, "above described" should read --above-described--; and

Line 57, "above described" should read --above-described--.

COLUMN 16

Line 8, "above described" should read --above-described--.

These errors appear to be relatively insignificant and, therefore, we do not

believe it is necessary to request a Certificate of Correction. However, it is requested that

this paper be placed in the filewrapper of the above-identified patent.

Patentee's undersigned attorney may be reached in our New York office by

telephone at (212) 218-2100. All correspondence should continue to be directed to our

address given below.

Respectfully submitted,

Leonard P. Diana

Attorney for Patentee

Registration No.: 29,296

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

Facsimile: (212) 218-2200

NY MAIN 517081v1

- 3 -